

Firmware Update (version 8.29) for Pioneer DVD Receivers

December 22, 2014

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 8.29) for the current lineup of Pioneer DVD receivers. This firmware update is only for the following Pioneer DVD receiver models, AVH-X1700S, AVH-X2700BS, AVH-X3700BHS, AVH-X4700BS and AVH-X5700BHS, sold in the United States and Canada. Installation on any other product could cause irreversible damage.

This firmware update (version 8.29) contains the following improvements:

- New added feature: AppRadio One
- Support for iDatalink[®] Maestro[™] compatibility
- Minor Bug Fixes

In order to perform this update, the following items are needed:

- Pioneer DVD receiver: AVH-X1700S, AVH-X2700BS, AVH-X3700BHS, AVH-X4700BS or AVH-X5700BHS
- A blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are attached. Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update:

- 1. Download the firmware update files to a computer from the Pioneer website: pioneerelectronics.com/firmware
- Transfer the files to the USB storage device for insertion into the Pioneer DVD receiver

Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 10:30 AM - 2:30 PM and 3:30 PM - 7:00 PM (Eastern Time), excluding holidays, or online through <u>parts.pioneerelectronics.com/contact</u>.

Sincerely,

Pioneer Electronics (USA) Inc.

iDatalink is a registered trademark of Automotive Data Solutions Inc.