AVIC-Z140BH and AVIC-X940BT Firmware Update (v4.600) for iPhone 5 AppRadio Mode Compatibility (October 2013) – APPLIES ONLY TO UNITS THAT HAVE NEVER BEEN UPGRADED

October 11, 2013

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a free firmware update for the Pioneer AVIC-Z140BH and AVIC-X940BT in-dash navigation systems. **This firmware update applies only to AVIC-Z140BH or AVIC-X940BT units sold in the United States and Canada, and where <u>the software has never been upgraded</u>.** This update contains the following improvement:

・iPhone 5 Compatibility for AppRadio Mode

This notice explains how to obtain the free firmware update for AVIC-Z140BH and AVIC-X940BT. **If you do not own an iPhone 5 or a 5th gen iPod Touch, there is no need to install this update.**

HOW TO OBTAIN THE FREE FIRMWARE UPDATE:

1. Download the firmware update files to a computer from the Pioneer website: **http://www.pioneerelectronics.com/PUSA/Support/Downloads**
2. Transfer the files to a SD card (for AVIC-Z140BH) or microSD card (for AVIC-X940BT) for insertion into to the navigation unit.

<u>Questions?</u>

If you have any questions, please contact the Pioneer Customer Service Center toll free at 1-800-421-1404. Pioneer service representatives are available Monday through Friday, 10:30 a.m. to 7:00 p.m. (Eastern Time), except on Holidays.

Sincerely,

Pioneer Electronics (USA) Inc.