



Firmware Update for Certain Pioneer In-Dash AV Receivers

June 19th, 2023

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update for **only the following Pioneer In-Dash AV Receivers sold in the United States and Canada**. Installation on any other product could cause irreversible damage.

DMH-T450EX/XNUC

This firmware update corrects the following matter.

- [Sound quality enhancements](#).

To perform this update, the following items are needed:

- Pioneer In-Dash AV Receiver
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32.

Instructions on installing the firmware are provided on the same page as the firmware update. Installation of the update should take about [three](#) minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
<https://www.pioneerelectronics.com/PUSA/Support/Downloads>
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through parts.pioneerelectronics.com/contact.

Sincerely,

Pioneer Electronics (USA) Inc.