



## Firmware Update (version 8.27) for Pioneer DVD Receivers

December 22, 2014

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 8.27) for the current lineup of Pioneer DVD receivers. **This firmware update is only for the following Pioneer DVD receiver models, AVH-X6700DVD and AVH-X7700BT, sold in the United States and Canada.** Installation on any other product could cause irreversible damage.

This firmware update (version 8.27) contains the following improvements:

- **New added feature: AppRadio One™**
- **Minor Bug Fixes**

In order to perform this update, the following items are needed:

- Pioneer DVD receiver: **AVH-X6700DVD or AVH-X7700BT**
- A blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are attached. Installation of the update should take no more than ten minutes to complete.

### How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website: [pioneerelectronics.com/firmware](http://pioneerelectronics.com/firmware)
2. Transfer the files to the USB storage device for insertion into the Pioneer DVD receiver

### Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 10:30 AM - 2:30 PM and 3:30 PM - 7:00 PM (Eastern Time), excluding holidays, or online through [parts.pioneerelectronics.com/contact](http://parts.pioneerelectronics.com/contact).

Sincerely,

**Pioneer Electronics (USA) Inc.**